

Photographs

Internal works



Window replacement



Water test



Phase 1 scaffolding removed to expose cladding installed.

